Summary Status of Prototype & Cosmic Testing

Megan Connors
Heal Meeting
January 26, 2016

General Status

- All inner and outer tiles have been tested with cosmics
 - Inner tiles in a box ready to be put into the assembly
- 150 SiPMs have wires attached ready to go (Megan needs to give Sal last 2 groups)
 - Will be added after installing tiles into the plates
- Plan for LEDs?

Inner Assembly Status

- Inner has outer skin
- Holes for inner skin done today
- Wedges cut ~done





Outer Hcal Assembly Status


- Steel plates stacked
- Tight spaces checked with "skinny" tiles...okay


car	Juter 3	ieei	Stack	Gap	vieast	ireme	iits
		4	5		6		
		4	3		0		
			TOP	.			
			101				
		1	2		3		
			upstre	am			
			upstic	aili			
Gap #1 is o	n the bottom						
		Mea	surement Po	sint			
Gap#	1	2	3 4		5	6	
1	9.03	9.05	8.85	8.83	8.83	8.62	
2	8.47	8.35	8.44	8.44	8.33	8.40	
3	9.07	9.03	8.90	8.77	8.85	8.87	
4	8.76	8.88	8.95	9.13	9.05	8.99	
5	8.26	8.20	8.37	8.30	8.34	8.47	
6	9.30	9.35	9.16	8.74	8.79	8.78	
7	8.28	8.22	8.27	8.78	8.77	8.71	
8	9.11	9.08	9.09	8.83	9.00	8.80	
9	9.10	9.33	9.06	8.98	9.01	8.79	
10	8.58	8.34	8.20	8.73	8.57	8.60	
11	9.13	9.20	9.23	8.97	9.14	9.23	
12	8.57	8.43	8.49	8.59	8.26	8.37	
13	9.19	9.38	9.33	9.18	9.26	9.08	
14	8.66	8.56	8.48	8.66	8.61	8.54	
15	8.97	9.04	9.13	8.86	8.88	8.79	



Cosmics Summary for the Inner


- Do we need to sort tiles based on light?
 - Will need to see what fits where...
 - Sorted by SiPM
- ~10% variation





Tile under pressure

- Mike applied 5 Tons of pressure to tile IH-1-38 (too thick to fit into assembly) for 3 days
- Compare cosmics from tile in stack before and after Pressure test



Different SiPM IH-1-37 Crushed Tile Different tile IH-1-40

Tile To Do's


- LED plans?
 - In SiPM holder? Drill to white?
- Put tiles into assembly
- Move cosmic test stand to high bay


Backup

Tile under pressure

Mike applied 5,000 lbs of pressur
 IH-1-38 (too thick to fit into asser

 Compare cosmics from tile in stage after Pressure test





Different SiPM IH-1-37 Crushed Tile Different tile IH-1-40